

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
MD,
4-BALT,
127A-

Baltimore & Ohio Railroad:
Mount Clare Shops
Baltimore
Baltimore Independent City
Maryland

HAER No. MD-6A

NOTE: These photographs are Government materials and not subject to copyright. However, the courtesy of a credit line identifying the Historic American Engineering Record and the photographer would be appreciated. All photographs were taken by William Edmund Barrett in 1976.

- MD-6A-1 VIEW OF FRONT ELEVATION OF HORSE STABLES LOOKING SOUTHEAST.
- MD-6A-2 3/4 VIEW OF FRONT ELEVATION OF STABLES LOOKING EAST, SHOWING EXAGGERATED VIEW OF 3-1/2 STORY, CENTER PEDIMENTED SECTION.
- MD-6A-3 VIEW OF FRONT ELEVATION OF STABLES LOOKING EAST.
- MD-6A-4 VIEW OF 3-1/2 STORY, CENTER PEDIMENTED SECTION OF STABLES LOOKING EAST.
- MD-6A-5 VIEW OF STABLES FROM OUTSIDE SHOPS COMPLEX FROM THE INTERSECTION OF JAMES AND OSTEND STREETS LOOKING NORTH.
- MD-6A-6 INTERIOR VIEW OF STABLES SHOWING HORSE STALLS.
- MD-6A-7 INTERIOR VIEW OF STABLES SHOWING HORSE STALLS LOOKING DOWN OPPOSITE WING.
- MD-6A-8 DETAIL VIEW OF HORSE STALL.
- MD-6A-9 DETAIL VIEW OF FEEDING TROUGH INSIDE HORSE STALL.
- MD-6A-10 VIEW OF BOILER SHOP FROM TOP OF BOX CAR WITH CIRCULAR CAR SHOP IN BACKGROUND LOOKING NORTHEAST.
- MD-6A-11 VIEW OF CIRCULAR CAR SHOP OVER TOPS OF BOX CARS LOOKING NORTHEAST.
- MD-6A-12 GENERAL VIEW OF BLACKSMITH SHOP (LEFT) AND CENTRAL POWER PLANT (RIGHT).
- MD-6A-13 INTERIOR VIEW OF CENTRAL POWER PLANT SHOWING TOP OF HOPPERS WHERE COAL WAS UNLOADED.
- MD-6A-14 DETAIL VIEW OF STEAM VALVES INSIDE CENTRAL POWER PLANT.

Baltimore and Ohio Railroad:
Mount Clare Shops
HAER No. MD-6A
Index to Photographs
(Page 2)

MD-6A-15 DETAIL VIEW OF MANUFACTURER'S MONOGRAM ON PIECE OF UNIDENTIFIED EQUIPMENT.

MD-6A-16 VIEW LOOKING DOWN WALKWAY INSIDE CENTRAL POWER PLANT SHOWING BOTTOM OF COAL HOPPERS.

MD-6A-17 VIEW LOOKING DOWN WALKWAY INSIDE CENTRAL POWER PLANT.

MD-6A-18 DETAIL VIEW OF FIRE ALARM SYSTEM BOARD THAT LISTS AREAS IN SHOPS COMPLEX.

MD-6A-19 VIEW INSIDE BOILER HOUSE OF CENTRAL POWER PLANT.

MD-6A-20 VIEW OF BOILERS INSIDE CENTRAL POWER PLANT.

MD-6A-21 VIEW OF BOILERS INSIDE CENTRAL POWER PLANT.

MD-6A-22 VIEW OF UNIDENTIFIED RESIDENTAL-LOOKING BUILDING THAT MAY HAVE BEEN USED FOR OFFICES LOCATED ALONGSIDE TRACKS ON SOUTHEAST EDGE OF SHOPS COMPLEX.

MD-6A-23 VIEW OF CENTRAL POWER PLANT UNDER DEMOLITION.

MD-6A-24 DETAIL VIEW OF CAST-IRON MAKER'S PLATE ON CHIMNEY IDENTIFYING "ALPHONS CUSTOBIS CHIMNEY CONSTRUCTION CO., BENNETT BUILDING, NEW YORK."

MD-6A-25 CAST-IRON WINDOW SILL OF PATTERN STORAGE BUILDING MARKED "B&ORR 1982."

MD-6A-26 VIEW OF PATTERN STORAGE BUILDING LOOKING NORTHWEST FROM TOP OF BOX CAR.

MD-6A-27 VIEW OF PATTERN STORAGE BUILDING LOOKING NORTHWEST FROM GROUND LEVEL.

MD-6A-28 VIEW OF FOUNDRY SAND BLASTING AND CLEANING BUILDING UNDER DEMOLITION.

MD-6A-29 DETAIL VIEW OF FOUNDRY SAND BLASTING AND CLEANING BUILDING UNDER DEMOLITION.

MD-6A-30 VIEW OF DEMOLITION OF FOUNDRY SAND BLASTING AND CLEANING BUILDING FROM INSIDE FOUNDRY.

MD-6A-31 VIEW OF DEMOLITION OF FOUNDRY SAND BLASTING AND CLEANING BUILDING FROM INSIDE FOUNDRY.

Baltimore and Ohio Railroad:
Mount Clare Shops
HAER No. MD-6A
Index to Photographs
(Page 3)

MD-6A-32 VIEW OF DEMOLISHED FOUNDRY SAND BLASTING AND CLEANING BUILDING
AFTER DUST HAS SETTLED.

MD-6A-33 VIEW OF ROOF TRUSSING SYSTEM OF SAND BLASTING AND CLEANING
BUILDING.

MD-6A-34 INTERIOR VIEW INSIDE PARTIALLY DEMOLISHED SAND BLASTING AND
CLEANING BUILDING LOOKING AT THE ELEVATION OF FOUNDRY.

MD-6A-35 VIEW OF END ELEVATION OF FOUNDRY LOOKING WEST.

MD-6A-36 VIEW OF END ELEVATION OF FOUNDRY LOOKING NORTH.

MD-6A-37 3/4 VIEW OF SOUTH ELEVATION OF FOUNDRY LOOKING NORTHWEST.

MD-6A-38 INTERIOR VIEW OF FOUNDRY SHOWING HEAVY TIMBER ROOF TRUSSES AND
TRAVELING CRANE.

MD-6A-39 SAME VIEW AS MD-6A-38, ONLY WITH A HORIZONTAL ORIENTATION.

MD-6A-40 DETAIL VIEW OF FOUNDRY HEAVY TIMBER ROOF TRUSSING SYSTEM.

MD-6A-41 DETAIL VIEW OF TRIPLED, HEAVY TIMBER TRUSSES IN FOUNDRY.

MD-6A-42 DETAIL VIEW OF TRIPLED, HEAVY TIMBER TRUSSES IN FOUNDRY.

MD-6A-43 DETAIL VIEW OF TRIPLED, HEAVY TIMBER TRUSSES IN FOUNDRY.

MD-6A-44 CAST-IRON WALL END PROTECTOR IN FOUNDRY BUILDING MARKED
"B&ORR Co. 1864."

MD-6A-45 VIEW OF FOUNDRY UNDER DEMOLITION.

MD-6A-46 VIEW OF CROSS-SECTION OF FOUNDRY BUILDING SHOWING ROOF TRUSSING
SYSTEM THAT WAS REVEALED DURING DEMOLITION.

MD-6A-47 DETAIL OF PAIRED, HEAVY-TIMBER TRUSSES IN FOUNDRY.

MD-6A-48 VIEW OF FOUNDRY UNDER DEMOLITION LOOKING SOUTHEAST.

MD-6A-49 INTERIOR VIEW OF BRASS FOUNDRY DURING DEMOLITION.

MD-6A-50 INTERIOR VIEW LOOKING SOUTH DOWN LENGTH OF BRASS FOUNDRY.

MD-6A-51 VIEW OF BLACKSMITH SHOP LOOKING NORTHWEST.

MD-6A-52 VIEW OF BLACKSMITH SHOP HALF-DEMOLISHED LOOKING NORTHWEST.

Baltimore and Ohio Railroad:
Mount Clare Shops
HAER No. MD-6A
Index to Photographs
(Page 4)

MD-6A-53 VIEW OF BLACKSMITH SHOP BUILDING DEBRIS.

MD-6A-54 INTERIOR VIEW OF BLACKSMITH SHOP BEFORE DEMOLITION.

MD-6A-55 LARGE, CAST-IRON BASE OF UNIDENTIFIED PIECE OF EQUIPMENT LOCATED IN RUINS OF BLACKSMITH SHOP.

MD-6A-56 VIEW OF SITE OF BLACKSMITH SHOPS ALONG CAREY STREET FOLLOWING DEMOLITION.

MD-6A-57 VIEW OF SITE OF BLACKSMITH SHOPS ALONG CAREY STREET FOLLOWING DEMOLITION.

MD-6A-58 VIEW OF PILE OF DEBRIS OF BLACKSMITH SHOP.

MD-6A-59 GENERAL VIEW OF SHOP COMPLEX IN THE VICINITY OF THE NORTHWEST CORNER.

MD-6A-60 GENERAL VIEW IN THE AREA OF BLACKSMITH SHOP AND BRASS FOUNDRY.

MD-6A-61 DETAIL VIEW OF CAST-IRON WALL BOLSTER MARKED "B&O BRIDGE SHOP MAY 1882."

MD-6A-62 CAST-IRON WALL BOLSTER MARKED "B&O BRIDGE SHOP MAY 1882."

MD-6A-63 DETAIL VIEW OF LIGHT METAL TRUSSING SYSTEM ON PARTIALLY DEMOLISHED GABLE END OF UNIDENTIFIED BUILDING.

MD-6A-64 INTERIOR VIEW LOOKING DOWN LENGTH OF AIR CONDITIONING EQUIPMENT REPAIR SHOP.

MD-6A-65 VIEW OF IRON FOUNDRY FROM CORNER OF CAREY AND PRATT STREETS LOOKING SOUTHEAST

MD-6A-66 VIEW OF PATTERN STORAGE BUILDING FROM ACROSS PRATT STREET LOOKING SOUTHEAST.